

CASE STUDY

New Vernon Bank

GEOGRAPHICAL AREA:

New Llano, Louisiana

ISSUE:

Condensation on skylight was causing water to drip onto the lobby floor.

SOLUTION:

EnergyProtect™

Coverage: 3-coats

RESULTS:

- ✓ Eliminated condensation
- ✓ Clear coating allows visible light to shine through and illuminate the lobby.
- ✓ Provides UV Resistance.
- ✓ Long Lasting 5-10 Years.

Award Winning Energy Saving and Asset Protection Coatings



Synavax™ thermal insulation and protective coatings were used to solve a critical condensation issue on the framing around the skylight which was causing dripping into the bank lobby.

The coating was used over the skylight and aluminum frame to eliminate the condensation and also reduce glare and heat loss and gain through the skylight.

-The Vernon Bank
New Llano, LA

