

CASE STUDY

Residential Application- Exterior wall

GEOGRAPHICAL AREA:
Kosice, Slovakia

ISSUE:

Experiencing mold growth after installation of plastic windows.

SOLUTION:


HomeProtect™ clear coat

Coverage: 3-coats

RESULTS:

- ✓ Provided a clear coating that would not hinder the look of the building.
- ✓ Provided thermal resistance, resulting in less moisture buildup on the interior and eliminating mold growth.
- ✓ Surface protection- mold, moisture and UV resistant.
- ✓ Long lasting 5-10 years

Award Winning Energy Saving and Asset Protection Coatings



- Customer Quote -

"Problem: I live in a 40-year old block of apartments. After installing new plastic windows in my apartment, I experienced mold on the interior side of the wall in close surrounding to the windows.

I applied HomeProtect™ Clear Coat to the exterior side of the wall, because I believe insulation from the exterior side is more efficient. Application was made in the beginning of March - early Spring in our area.

After application, mold stopped growing. I will see how it works also during next winter when the problem is most visible, but I believe that it will work. I tried your paint because we cannot agree with other owners of our apartments about total reconstruction of the facade (polystyrene or mineral wool systems), so I was forced to protect my wall individually."

Martin Tancák
Kosice, Slovakia