



CASE STUDY

Hyundai Corporate Housing

Award Winning Energy Saving and Asset Protection Coatings

GEOGRAPHICAL AREA:
Seoul, South Korea

ISSUE:

Condensation buildup in hallways of lower levels.

SOLUTION:

EnergyProtect™

Coverage: 3- Coats

RESULTS:

- ✓ Provided alternate form of insulation for walls and ceilings.
- ✓ Helped to reduce condensation buildup in hallways of building.
- ✓ Provided resistance to mold and moisture damage.
- ✓ Clear coating allows for original surface to shine through.
- ✓ Long lasting 5-10 years.



These luxury apartments owned by Hyundai had an issue with condensation on the lower levels, and also needed an innovative way to increase energy efficiency of the building without giving up additional interior space.

Our patented EnergyProtect™ translucent coating was applied in 2005 to internal walls and ceilings to offer the needed protection from condensation and mold in a cost effective application.

The coating also increased the thermal resistance of the building, thus lowering energy costs for the owner.

